

MEMS VCSEL Utility Changelog

Contents

Semantic Versioning	1
Changes in version 2.3.x	2

Semantic Versioning

Given a version number MAJOR.MINOR.PATCH, we follow the rules:

1. Increase MAJOR version when we make incompatible API changes,
2. Increase MINOR version when we add functionality in a backwards compatible manner, and
3. Increase PATCH version when we make backwards compatible bug fixes.

Changes in version 2.3.x

Version 2.3.1

New features and enhancements

- -

Major bug fixes

- Replaces deprecated interface calls to find COM-Port device

Changes on environment

- -

Version 2.3.0

New features and enhancements

- Adds Support for SZ Systems
- Enables Error Code Display
- Allows Mode Config switches
- Enables instantaneous Delay and Power Adjustments without requirement for 'Save' Button press
- Adds sweep rate display
- Updates drivers to run on Win11

Major bug fixes

- -

Changes on environment

- -